



MBScope E300V2 Change Log

v1.4.5 September 22, 2017

Minor Features:

- Feature 1652: [PL209] Factory Configuration Panel - Add the "Browse" buttons in the Application Settings view to choose the MDL files

Bugs:

- Bug 2944: Event Viewer - Unable to open a specific SDR due to an IniFileReaderException
- Bug 3094: [PL209] Factory Configuration Panel - Correction to the SPV Position Offset Calculation
- Bug 3095: [PL682] Event Viewer - Data is flatlined
- Bug 3092: Factory Configuration Panel - Problem with Hn filter configuration

v1.4.4 July 13, 2017

Bugs:

- Bug 2899: Observer Link Memory Leak - Fixed "Null Reference Exception" in the real-time data manager caused by computation of estimated voltages.

v1.4.3 May 5, 2017

Minor Features:

- Feature 1440: MBDataEngine, Snapshots, Trending and Event Viewer tools - Replaced Estimated Bearing Voltage channels by Estimated Amplifier Voltage channels
- Feature 1442: Parameter Loader - Removed the .NTW and .PTX files generated by the parameter loader
- Feature 1443: MBDataEngine - Added update of the CRC calculation when changing DSP and SPV parameters in Offline Mode
- Feature 1445: Installer - Execute the Digi-Connect installer when installing the CD
- Feature 1463: Parameter Loader - Updated progress bar to display parameter loader steps. Loading of parameters to each target (DSP, SPV and MBCSI) and store to flash progress for DSP and SPV targets
- Feature 1476: OEM Config. Panel - Added PT100 temperature offset calibration to the BNC Configuration tab and removed it from the General Information tab

Bugs:

- Bug 2830: Fixed exception thrown in Snapshots when a duplicate channel was added to the same snapshots window
- Bug 2878: Fixed Parameter Loader receive button not working when MBCSI parameters were selected
- Bug 2882: Fixed a configuration Panel problem where the wrong PEF will be selected when using a PVFz in Offline Mode
- Bug 2891: Fixed Estimated Amplifier Voltage calculation for axial axis in the MBDataEngine
- Bug 2892: Fixed Estimated Amplifier Voltage calculation for Z2 axis
- Bug 2894: Fixed navigator window in the Trending tool when the FFT view is active
- Bug 2904: Fixed final elongation calculation in the clearance tab of the Service Panel

v1.4.2 March 3, 2017

Minor Features:

- Feature 1358: Configuration Panel - (Offline Mode) Synchronize modifications to files stored in PVFz

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com



- Feature 1436: Configuration Viewer - Separate out 'Send' and 'StF' actions
- Feature 1444: Control Panel - Add display of the DSP and SPV checksums
- Feature 1364: [PL864] Event Viewer - ASD files improvement
- Feature 1434: [ID143] Add new MBCSI 'Starting' event

Bugs:

- Bug 2790: Support for Windows 100%/125%/150% Scaling
- Bug 2874: Calibration Tool and Service Panel - Store to Flash Fails
- Bug 2820: TSD & ASD files - the last line of data is not read
- Bug 2758: MBDE - Memory leak when cabinet is not connected, but plugin is trying to connect
- Bug 2779: MBDE - Snapshot frame detection is not detecting when the counter wrapped
- Bug 2780: MBDE - Snapshot start time was not getting sent to the plugin manager correctly
- Bug 2729: MBDE - Estimated bearing voltage calculation can fail & spam the log
- Bug 2803: MBScope Settings - The log level configuration did not work
- Bug 2822: [PL682] Event Viewer - Data issue in the ASR file
- Bug 2821: [PL683] Control Panel - Remove the high/low limit for unbalance display
- Bug 2866: [ID151] Event Viewer - Display the peak positions from the SDR file of SPV
- Bug 2867: [ID151] Configuration Panel - Disable parameters (excepted the clear auto) in the MBCSI parameter view in offline mode

v1.4.1 Jan 13, 2017

Minor Features:

- Feature 1351: Analyzer - Change the default injection parameters
- Feature 1352: Service Panel - Change the default naming convention
- Feature 1378: Configuration Panel - Change 'Min Clearance' display to a 'Mechanical Airgap' display instead

Bugs:

- Bug 2691: Event Viewer - SDR save is not available
- Bug 2693: Service Panel - Decrypted files are not downloaded from MBCSI
- Bug 2721: Service Panel - Allow Certified Users to take transfer functions while rotating
- Bug 2697: Calibration Panel - Icons are huge and blurry
- Bug 2709: Trending Tool - TPL files should not save a default output folder
- Bug 2692: Configuration Viewer - Send to Controller Store to Flash function is not always working
- Bug 2651: Launcher - Update the Help > Send Diagnostic Info button
- Bug 2732: @Observer Link - Missing packet detection

v1.4.0 Dec 21, 2016

Major Features

- Feature 1232: Auto Connect on start option
- Feature 1197: Service Panel - Record Machine Status
- Feature 1203: Event Viewer - FFT View
- Feature 1233: Offline Mode with a PVFz
- Feature 1202: Service Panel & Analyzer - Include Rotation Speed Simulation option

Minor Features

- Feature 1199: Service Panel & Analyzer - Option to include/exclude TSD data along with ANL data
- Feature 1198: Service Panel - Allow axis-by-axis levitation
- Feature 1200: Service Panel - Choose from a list of template files to use

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com

- Feature 1196: Service Panel – Allow of certified users to modify the gains
- Feature 1367: Service Panel – Allow Certified Users to view the Open Loop TF
- Feature 1204: Parameter Loader – Include the PTX and NTW files
- Feature 1357: Parameter Loader – Add the 'Bearing_Characteristics.DAT' file into the PVFZ
- Feature 1362: Configuration Viewer – Display of the centering compensation
- Feature 1373: Configuration Viewer – Allow access to this panel only for Certified Users
- Feature 1354: Signal Generator – Change the default injection frequency to 10Hz

Bugs

- Bug 2668: Configuration Viewer – Ref Shift and Sens Gains modifications are not getting applied
- Bug 2676: Configuration Viewer – When sending all parameters, ensure levitation is off
- Bug 2683: Trending – Locking up when stopping the trend
- Bug 2685: Parameter Loader – Reference Shift and Sensitivity Gains modifications are not getting applied
- Bug 2681: Service Panel – Phase graph does not have the same operation as Analyzer (locked to +/-180deg)
- Bug 2689: Service Panel – Do not default/change TF selection when starting a sweep
- Bug 1740: Event viewer – No Dialog box to save SDR files
- Bug 2629: Analyzer – Injection Channels wrong when force injection point selected
- Bug 1750: Encryption – MDL files are not handled by encryption
- Bug 2096: Snapshots – FFT loses resolution when a snapshot is saved
- Bug 2097: Snapshots – When a Snapshots is opened (time domain) the spectrum option should be disabled.
- Bug 2291: Launcher – Remove 'update' buttons
- Bug 2299: Failed parameter queries are not caught by the MBDataEngine
- Bug 2303: Trending – Even though the trend is complete, the Events will keep increasing and the Disk Space decrease.
- Bug 2337: E300V2 – Add support for Release Candidate Checking
- Bug 2338: Voltage Estimation – Axial calculation can be wrong due to invalid FSV
- Bug 2352: Licensing – Multiple license keys cause very slow loading.
- Bug 2378: Event Viewer: Moved custom display as utc option to the global UI interface
- Bug 2390: Event Viewer – Wrong Icon
- Bug 2463: Configuration Panel – Leaving and Reentering a tab will return "Changed" boxes back to the original color
- Bug 2626: Trending – Auto Scale does not work correctly with two Y Axis
- Bug 2631: Snapshots: Tool crashing when changing spectral estimation factor
- Bug 2636: Service Panel – Send Offset + StF does not store new offset values in DSP and SPV
- Bug 2646: Service Panel – Clearance Check via Inflection Method is not working for radial
- Bug 2653: Service Panel: Crash when opening a TF template with certified license
- Bug 2660: Configuration Viewer – Rename 'Oscillator Offsets Plane' to 'Reference Shift'
- Bug 2661: Configuration Viewer – Panel is not large enough to show all information on the Amplifier tab
- Bug 2662: Calibration Panel – Inflection Point method: Amp Cmd (%) limits should be restrained to 0 - 100%
- Bug 2663: Calibration Panel – Inflection Point method: Amp Cmd (%) limits are not respecting the manual axis settings
- Bug 2673: Config Viewer – Global Gain is not working
- Bug 2228: MBDE Exception – InvalidOperationException in RTDataManager
- Bug 2549: Machine Speed: Not updated in analyzer and ono files
- Bug 2609: [PL570] Control Panel – allow to levitate after a store to flash in DSP
- Bug 2610: [PL630] Control Panel – Modify the "clear F1" and "clear F2" labels by "Clear Level 1" and "Clear Level 2".
- Bug 2611: [PL634] Control Panel – Add the status of the customer status HIO
- Bug 2612: [PL671] Control Panel – Disable the disk space used
- Bug 2647: Configuration Panel – Reference Shift is not correctly processing values

v1.3.1

Sept 23, 2016

- Feature 1299: Calibration & Service Panel – Support for 4 Axis Systems

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com

v1.3.0 July 22, 2016

- Feature 1084: Trending – FFT View for TSD files
- Feature 1104: Added Bearing Voltage Estimation real time channels to the Snapshot, Trending and Event Viewer tools
- Feature 1144: Added a R/W mode to the Configuration Viewer
- Feature 1159: [S2M] PL60: Configuration Panel – Configure Bearing Characteristics
- Feature 1171: [S2M] [S2M] PL650: Configuration Panel – Properly display the 1st or 2nd order bearing filter dialog
- Feature 1180: [S2M] PL639: Allow to save the SDR file and LR file directly. Possibility to open a SDR file or LR file recorded in the PC.
- Feature 1228: [S2M] PL574: Modify the labels of events for the Power Supply
- Feature 1230: [S2M] PL652: Control Panel – Display of harmonic rank
- Feature 1238: [S2M] PL660: Add new Enum to read the rank of the harmonic
- Bug 1817: Memory leak during reconnection process, when not able to connect
- Bug 2092: Trending – Cursor shouldn't be a waiting glass in the Triggered/Collected box
- Bug 2093: Trending – When channels have decimation, the duration time of the sample is wrong.
- Bug 2185: Trending – Icon is incorrect
- Bug 2215: Calibration Panel – Auto Centering does not update DAC_OFFSET1 parameters
- Bug 2216: [S2M] PL648: Config Panel – Modify the label for the Elongation in the Configuration Hardware view
- Bug 2270: [S2M] PL652: Control Panel – Improve the display for the harmonics
- Bug 2286: [S2M] PL651: Event file in MBCSI are not downloading
- Bug 2307: Trending – Some channels at the end of the list cannot be displayed
- Bug 2269: Analyzer – Unable to open V6 files
- Bug 2310: Analyzer – Unable to open V7 files
- Bug 2311: Calibration Panel – The centering parameters are not updated into the centering Position Offset block of SPV
- Bug 2312: Event Viewer – Cannot open SDR when offline
- Bug 2061: Trending – Disconnect does not work (Unhandled Application Exception)
- Bug 2064: Parameter Loader – Missing User's Guide in Help menu

v1.2.2 May 6, 2016

- Feature 1037: Analyzer – Opens several files in one shot
- Feature 1036: Analyzer – Export only direct transfer functions
- Bug 1946: Update to MBLicense v5.1.1 to fix the 'changing PCID' issue
- Bug 2040: Trending Tool – Y value not display in the cursor tool tiup when HHMMSS time format selected
- Bug 1939: Snapshots – SSD files are not scaling correctly
- Bug 2034: Snapshots – Saving Amplifier Current SSD causes an OutOfIndexArrayException
- Bug 1907: Snapshots – Label "Position Z1" rename to "Position Z"
- Bug 1942: Service Panel – Power time date format has hours and seconds swapped
- Bug 2039: Service Panel – Levitation counter not updating
- Bug 1961: Service Panel – Date Time Bug Fix
- Bug 2038: Analyzer – Multiple Selection not working
- Bug 1940: Analyzer – Avoid exporting empty transfer functions
- Bug 2036: PL625 – Configuration Panel – Some views are in error when not connected
- Bug 1972: PL622 – Control Panel – Display the Harmonics information from DSP Control Panel
- Bug 1971: PL621 – Configuration Panel – Manage the command for automatic auto batteries test
- Bug 1974: PL604 – Firmware Loader – SPV firmwareload without having another panel opened
- Bug 1973: PL574 – Event Viewer – Events for PCS modified
- Bug 1868: Service Panel – Fixed access for license level permissions

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com

v1.2.1 February 12, 2016

- Bug 1868: Service Panel – Fixed access for license level permissions

v1.2.0 February 5, 2016

Major Features:

- Feature 981: Configuration Viewer – Initial Release
- Feature 921: Parameter Loader – Addition of MBCSI files
- Feature 1006: Parameter Loader – SPV and DSP now Store to Flash when sending parameters
- Feature 975: Analyzer & Service Panel – Support for ONO export
- Feature 922: Service Panel – Added Touch and Go

Bugs & Smaller Features:

- Feature 1007: Calibration Tool – When choosing triangular distortion method, it is not possible to choose the shape between sine and triangular waveform
- Bug 1630: Orbits – API/Clearance Limits – Available for Currents and Requests
- Bug 1636: Calibration Tool – Error writing INI file
- Bug 1637: Configuration Panel – does not support 64-bit
- Bug 1726: Configuration Panel – Encrypted PEF not supported
- Bug 1749: Service Panel – Offsets not saved into permanent memory
- Bug 1752: Calibration – API Display Limits – incorrect
- Bug 1811: Configuration Viewer – Some sections missing
- Bug 1823: Configuration Panel – NTW files not working
- Bug 1834: Analyzer – Unable to display open loop and closed loop at the same time
- Bug 1836: PL606 – Configuration Panel – Bug fixed for the unbalance FSV
- Bug 1837: PL577 – Configuration Panel – Display the rotor status for all panels
- Bug 1838: PL517 – Add new event for the maintenance key
- Bug 1839: PL610 – Configuration Panel – Add Touch & Go for axial
- Bug 1840: PL609 – Configuration Panel – Add new DO management for rotor rotation in the Configure Hardware View
- Bug 1841: PL612 – Event Viewer – Add units in the bar description for Alarm Snapshot & MBCSI LF Trending
- Bug 1842: PL611 – Event Viewer – Save the MBCSI event log
- Bug 1843: PL611 – Event Viewer – Save the SDR files & Low Frequency files in text format
- Bug 1844: PL612 – Event Viewer – Display the magnitudes & the phases for the SDR & Low frequency data
- Bug 1859: Service Panel – Choosing template with sinewaveform, triangular waveform gets driven by DSP

v1.1.0 December 16, 2015

- Bug 1096: Orbits – An exception occurred if the manual radius entry was too large
- Bug 1114: Firmware Loader – An exception occurred if no file was selected to send
- Bug 1115: Calibration Panel – An exception occurred if the step size entry was too large
- Bug 1646: Calibration Panel – Unable to auto-calibrate
- Bug 1692: E300V2 label in the status bar is in the wrong place
- Bug 1694: Configuration Panel – Exception when launched
- Bug 1712: Configuration Panel – Exception when sending the scaling factor
- Feature 902: Added build information to all output files
- Feature 988: Added Encryption to all MBScope files (encrypted files have a '#' appended)
- Feature 328: Added API display limits to the Snapshots, Orbits, Analyzer, and Calibration tools
- Feature 718: Moved all user files from "C:\Program Files\" to "C:\ProgramData\"
- Feature 930: Added a new Logging Options and Logging Export feature(Figure 1)
- Feature 931: Added a better UI for importing MDLs and PEFs (Figure 2)

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com




Figure 1 – Logging Options Feature (via the User Interface Settings)




Figure 2 – Send diagnostic & logging information, and Import PEF/MDL features (via the Launcher)

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com
 Phone: +1 403 232 9292
www.skfmagneticbearings.com

v1.0.7 November 12, 2015

- Bug 1564: Configuration Panel – Fixed issues with data boxes not accepting and clearing data entered by user after sent to the controller
- Bug 1565: Firmware Loader – Fixed issue where the SPV image won't be sent to the controller
- Bug 1514: Service Panel – Fixed issue where a change in the output folder from the Transfer Functions Tab crashes the tool.
- Bug 1568: Service Panel – Fixed issue that does not allow calibration of Z axis when multiple axes are selected in template
- Bug 1573: Event Viewer – Improved the display for Hard/Soft landing counters
- Bug 1593: Control Panel – Added display for temperatures not available
- Bug 1594: Configuration Panel – Added dropping of shaft and writing to SPV during rotation and Improved the AO configuration display.

v1.0.6 September 25, 2015

- Bug 1362: Installation – Changed 'Params' folder to 'Param'
- Bug 1339: Installation – Upgrading deleted the PEF folder
- Bug 1138: Snapshots – Fixed issues with horizontal scaling in spectrum view
- Bug 1304: Snapshots – Snapshots Start/Stop button has incorrect text when pressing 'Single'
- Bug 1248: Control Panel – Fixed exception when opening the monitoring panel
- Bug 1283: Calibration Tool – Fixed Store to Flash issues
- Feature 763: Event Viewer – Added a new event for 'Counter Reset'
- Feature 768: Event Viewer – Added a new event for 'Battery Unplugged'
- Feature 764: Event Viewer – Added a new event and alarm for 'Battery Life'
- Feature 765: Event Viewer – Improve display of the SPV SDR
- Feature 766: Event Viewer – Add a new tab to display LF data from MBCSI
- Feature 765: Event Viewer – Add a new tab to display the event saved in the MBCSI
- Feature: Upgraded the Math Calculation Library

v1.0.5 August 21, 2015

- Bug 1284: Service Panel – Failed detection when switching axis
- Bug 1282: Service Panel – Fixed output file name for transfer function tab
- Bug 1300: Firmware Loader – Removed the requirement for admin privileges
- Feature 703: Installation – Addition of 'Params' folder in MBScope root directory

v1.0.4 July 15, 2015

- Bug 1211: Analyzer Tool – Fixed channel naming in ANL file data header
- Bug 1213: Calibration Panel – Fixed the display of an error during some configurations
- Bug 1214: Service Panel – Fixed an error message that sometimes occurred at the end of a measurement with a template, and fixed the sometimes missing open loop display.
- Bug 1231: Event Viewer – Small operational fixes
 - Added battery unplug events
 - Added event for maintenance key timeout
 - Removed display of axis that are not available in the machine

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com

Phone: +1 403 232 9292

www.skfmagneticbearings.com

v1.0.3 July 2, 2015

- Bug 1197: Configuration Panel – Clear the Calibration Save after DSP Store to Flash
- Bug 1186: MBPlugin Manager Icon is incorrect
- Bug 1147: Misplaced text on the installer screen

v1.0.2 June 17, 2015

- Bug 1141: Small operational fixes
 - Configuration Panel: Fixed the entry of detection threshold for SPV Overspeed
 - Configuration Panel: Delete temporary files after use
 - Firmware Loader: Fixed which file types are displayed when browsing for MBCSI files
- Bug 1146: MBPlugin Manager was missing from the Start Menu and Launcher

v1.0.1 June 5, 2015

- Bug 1098: Memory leak during MBC reconnection process
- Bug 1106: Calibration Panel - Corrected the cross weight equation
- Bug 1109: Configuration Panel & Control Panel - Small operational fixes
- Bug 1111: Fixed project build issues

v1.0.0 May 29, 2015

Baseline Release

If you require technical support please contact us at the following:

Email: magnetic.bearings@skf.com
Phone: +1 403 232 9292
www.skfmagneticbearings.com